Enquiry Number: 522539

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: LED Project

Site: VICTORIA DRIVE

Location: Outside No 5

Service: Street Lighting

Recorded Date: 01-Sep-2020 Last Logged Date: 03-Sep-2020

Response Date : Completion Target :

Enquiry Number: 522639

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Road Damaged By 3rd Party

Site: LANCER DRIVE

Location: As road not only bends round but also narrows outside 4 Lancer Drive.

Service: Road/Carriageway

Recorded Date: 02-Sep-2020 Last Logged Date: 08-Sep-2020

Response Date : Completion Target :

Enquiry Number: 523579

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Blocked Drain/Gully

Site: REDWELL GROVE

Location: Two blocked drains outside No.19 Redwell Grove ME19 4BU. One created a small pool of water during

recent heavy rain.

Service: Drainage and Flooding

Recorded Date: 07-Sep-2020 Last Logged Date: 24-Sep-2020

Response Date : Completion Target :

Enquiry Number: 523583

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public
Subject: Dip/Depression
Site: REDWELL GROVE

Location: Pavement outside 19 Redwell Grove. ME19 4BU.

Service: Road/Carriageway

Recorded Date:07-Sep-2020Last Logged Date:09-Sep-2020Response Date:07-Oct-2020Completion Target:06-Oct-2020

30-September-2020 Page 1 of 8

Enquiry Number: 523585

Outstanding: N Enquiry Status: Work has been planned as part of our schedule and will

be undertaken shortly

Customer Type: Member of Public
Subject: Mud On Road

Site: REDWELL GROVE

Location: Large area of weeds and grass growing in the road by dropped kerb.

Service: Road/Carriageway

Recorded Date: 07-Sep-2020 Last Logged Date: 10-Sep-2020

Response Date: 07-Oct-2020 Completion Target:

Enquiry Number: 523703

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Damaged

Site: DISCOVERY DRIVE

Location: Pedestrian pathway outside 103 Discovery Drive is dangerously uneven and broken The paving blocks are

protruding making passage difficult for pedestrians and cyclists

Service: Footpaths/Pavements

Recorded Date: 08-Sep-2020 Last Logged Date: 10-Sep-2020

Response Date : Completion Target :

Enquiry Number: 523913

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Not Working
Site: LAPINS LANE

Location: Street light in front of 18 Lapins Lane not working.

Service: Street Lighting

Recorded Date: 09-Sep-2020 Last Logged Date: 21-Sep-2020

Response Date : Completion Target :

Enquiry Number: 523914

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public Subject: Not Working

Site: LAPINS LANE

Location: Street light in front of 18 Lapins Lane not working.

Service: Street Lighting

Recorded Date: 09-Sep-2020 Last Logged Date: 21-Sep-2020

Response Date : Completion Target :

30-September-2020 Page 2 of 8

Enquiry Number: 524101

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Manhole/Drain Cover Problem

Site: DISCOVERY DRIVE

Location: Good morning We have a loose manhole outside our house that makes a very loud noise keeps us

awake due to vehicles running over it. It is in the middle of the road which means that vehicles from both

directions are capable of running over it.

Service: Road/Carriageway

Recorded Date: 10-Sep-2020 Last Logged Date: 21-Sep-2020

Response Date : Completion Target :

Enquiry Number: 524102

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public
Subject: Shade Request
Site: DISCOVERY DRIVE

Location: Street light outside our house

Service: Street Lighting

Recorded Date: 10-Sep-2020 Last Logged Date: 24-Sep-2020
Response Date: Completion Target: 15-Oct-2020

Enquiry Number: 524446

Outstanding: N Enquiry Status: Not highways - passed to others

Customer Type: Member of Public
Subject: Utility Responsibility
Site: MITCHELL ROAD

Location: On pavement outside number 24 Mitchell Road adjacent to dropped driveway curb

Service: Section 81

Recorded Date: 11-Sep-2020 Last Logged Date: 21-Sep-2020

Response Date: 14-Oct-2020 Completion Target:

Enquiry Number: 524337

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public
Subject: Not Working
Site: WINDSOR ROAD

Location: Outside 14 Windsor Road front door, on public pavement

Service: Street Lighting

Recorded Date: 11-Sep-2020 Last Logged Date: 14-Sep-2020
Response Date: Completion Target: 22-Sep-2020

30-September-2020 Page 3 of 8

Enquiry Number: 524349

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public
Subject: Shade Request
Site: CLARENCE WAY

Location: The street light is in close proximity to the bedroom window on my property. A significant proportion of the

light radiates into the bedroom window. This is problematic on hot nights when it is desirable to leave the

shutters and curtains partly ope

Service: Street Lighting

Recorded Date: 11-Sep-2020 Last Logged Date: 14-Sep-2020

Response Date : Completion Target :

Enquiry Number: 524708

Outstanding: Y Enquiry Status: Enquiry under investigation

Customer Type: Member of Public

Subject: Needs Repair/Potholes etc.

Site: REGENT WAY

Location: its in path way pavements between 37 and 39 regent way, kings hill

Service: Footpaths/Pavements

Recorded Date: 14-Sep-2020 Last Logged Date: 16-Sep-2020
Response Date: 14-Oct-2020 Completion Target: 12-Oct-2020

Enquiry Number: 524847

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public
Subject: Shade Request
Site: WOODFORD GROVE

Site: WOODFORD GROVE

Location: Outside bedroom kitchen window

Service: Street Lighting

Response Date: 15-Sep-2020

Last Logged Date: 15-Sep-2020

Completion Target: 26-Sep-2020

Enquiry Number: 11811764

Outstanding: N Enquiry Status: Vehicle Crossing Application Approved

Customer Type: Member of Public

Subject: Application - New Residents

Site: BAXTER WAY

Location: 25 Baxter Way Kings Hill West Malling ME19 4DE

Service: Vehicle Crossing

Recorded Date: 15-Sep-2020 Last Logged Date: 24-Sep-2020

Response Date: 24-Sep-2021 Completion Target:

30-September-2020 Page 4 of 8

Enquiry Number: 525339

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public Subject: Not Working

Site: PIPPIN WAY

Location: opp 74 and opp junction with perergrine

Service: Street Lighting

Recorded Date: 17-Sep-2020 Last Logged Date: 18-Sep-2020

Response Date : Completion Target :

Enquiry Number: 525417

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public Subject: Shade Request Site: WINDSOR ROAD

Location: I requested a shield which had been installed but it does not shield our property No 3 Windsor Road front

upstairs bed room window

Service: Street Lighting

Recorded Date: 17-Sep-2020 Last Logged Date: 18-Sep-2020
Response Date: Completion Target: 22-Sep-2020

Enquiry Number: 525528

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public
Subject: Continually On
Site: VICTORIA DRIVE

Location: Streetlights are on continually in this street.

Service: Street Lighting

Recorded Date: 18-Sep-2020 Last Logged Date: 21-Sep-2020

Response Date : Completion Target :

Enquiry Number: 526032

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public

Subject: Damaged

Site: LAMBOURNE DRIVE

Location: in front of number 2 Lambourne Drive

Service: Footpaths/Pavements

Recorded Date:21-Sep-2020Last Logged Date:23-Sep-2020Response Date:19-Oct-2020Completion Target:21-Oct-2020

30-September-2020 Page 5 of 8

Enquiry Number: 526030

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public Subject: Not Working

Site: LAMBOURNE DRIVE

Location: Street lighting outside no.2 and outside no.4 Lambourne Drive

Service: Street Lighting

Recorded Date: 21-Sep-2020 Last Logged Date: 22-Sep-2020

Response Date : Completion Target :

Enquiry Number: 526329

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: Manhole/Drain Cover Problem

Site: FORTUNE WAY

Location: Outside number 11

Service: Drainage and Flooding

Recorded Date: 23-Sep-2020 Last Logged Date: 24-Sep-2020

Response Date : Completion Target :

Enquiry Number: 526384

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public
Subject: Maintenance query
Site: ROUGEMONT

Location: Rougemont, Kings Hill, ME19 4QD. We were told there would be weed control carried out in September

and we have seen this in operation within Kings Hill, however, yet again the whole of Rougemont has been

missed. Please ensure this is carried out.

Service: Weeds

Recorded Date: 23-Sep-2020 Last Logged Date: 25-Sep-2020

Response Date : Completion Target :

Enquiry Number: 526558

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public

Subject: New Connection Enquiry

Site: PIPPIN WAY

Location: 78, Pippin Way, Kings Hill, West Malling, ME19 4FQ

Service: Street Lighting

Recorded Date: 24-Sep-2020 Last Logged Date: 25-Sep-2020

Response Date : Completion Target :

30-September-2020 Page 6 of 8

Enquiry Number: 526749

Outstanding: Y Enquiry Status: Works being programmed

Customer Type: Member of Public

Subject: Needs Repair/Potholes etc.

Site: ALTON AVENUE

Location: Various uneven/sunken paving bricks pavement near to street light and front of 10 Alton Ave

Service: Footpaths/Pavements

Recorded Date: 25-Sep-2020 Last Logged Date: 29-Sep-2020

Response Date: 23-Oct-2020 Completion Target: 27-Oct-2020

Enquiry Number: 526873

Outstanding: Y Enquiry Status: Works being programmed

Customer Type : Member of Public Subject : Road Surface Cracked

Site: ALFA CLOSE

Location: A number of block pathing slabs loose and moving across the whole road making it very unsafe under foot

Service: Road/Carriageway

Recorded Date: 25-Sep-2020 Last Logged Date: 29-Sep-2020
Response Date: 26-Oct-2020 Completion Target: 27-Oct-2020

Enquiry Number: 526821

Outstanding: N Enquiry Status: Enquiry resolved

Customer Type: Member of Public Subject: Maintenance query Site: ATLAS CLOSE

Location: At the rear of 6 Atlas Close - Actually within The Discovery Schools grounds

Service: Trees

Recorded Date: 25-Sep-2020 Last Logged Date: 25-Sep-2020

Response Date : Completion Target :

Enquiry Number: 526822

Outstanding: Y Enquiry Status: Enquiry under investigation

Customer Type: Member of Public

Subject: Maintenance query

Site: ATLAS CLOSE

Location: At the rear of 6 Atlas Close - Actually within The Discovery Schools grounds

Service: Trees

Response Date: 25-Sep-2020

Last Logged Date: 25-Sep-2020

Response Date: 23-Oct-2020

Completion Target: 23-Oct-2020

30-September-2020 Page 7 of 8

Enquiry Number: 527308

Outstanding: Y Enquiry Status: Enquiry under investigation

Customer Type: Member of Public

Subject: Illuminated- not working/damge

Site: TOWER VIEW
Location: Broken bollard
Service: Bollards

Recorded Date: 29-Sep-2020 Last Logged Date: 29-Sep-2020

Response Date : Completion Target : 27-Oct-2020

30-September-2020 Page 8 of 8